FEDERAL COMMUNICATIONS COMMISSION 445 TWELFTH STREET SW WASHINGTON DC 20554

MEDIA BUREAU
AUDIO DIVISION
APPLICATION STATUS: (202) 418 2720

APPLICATION STATUS: (202) 418-2730 HOME PAGE: www.fcc.gov/mb/audio/

ENGINEER: CHARLES N. (NORM) MILLER

TELEPHONE: (202) 418-2767 FACSIMILE: (202) 418-1410 E-MAIL: charles.miller@fcc.gov

February 16, 2011

Gene W. Wisniewski World Radio Link, Inc. Box 5429 Twin Falls, Idaho 83003

Re: Horizon Christian Fellowship

K203EJ(FX), Goodland, Kansas

Facility Identification Number: 148860

Special Temporary Authority

Dear Dr. Wisniewski:

This is in reference to the request filed February 14, 2011, on behalf of Horizon Christian Fellowship ("HCF"). HCF requests special temporary authority ("STA") to operate FM Translator Station K203EJ with temporary facilities. In support of the request, HCF states that the licensed site has been lost, that the station currently is silent and that it faces the loss of its license if it does not resume broadcasting on or before February 18, 2011. HCF proposes operation of Station K203EJ from a nearby, existing tower with reduced power.

STA requests which involve a change in transmitter site must include four critical elements: (1) Loss of the licensed site must be beyond the licensee's control; (2) STA facilities must continue to provide service² to the licensed community; (3) STA facilities must maintain, as closely as practicable, the licensed service area³ without extending it; (4) STA facilities cannot involve the construction of towers intended for permanent use by the station requesting the STA. Our review indicates that the proposed STA operation complies with the foregoing criteria.

Accordingly, the request for STA IS HEREBY GRANTED. Station K203EJ may operate with the following facilities:

Geographic coordinates:

39° 20′ 48″ N, 101° 42′ 43″ W (NAD 1927)

Channel

203 (88.5 MHz)

Effective radiated power:

0.01 kilowatt (V only)

Antenna height:

above ground:

4 meters

above mean sea level:

1128 meters

¹ K203EJ is licensed for operation on Channel 203D (88.5 MHz) with effective radiated power of 0.25 kilowatt (H&V) and antenna height above average terrain of 68 meters.

 $^{^{2}}$ For AM - 5 mV/m; for commercial FM - 3.16 mV/m; for noncommercial educational FM - 1.0 mV/m.

³ For AM - 0.5 mV/m contour; for FM - 1.0 mV/m contour.

above average terrain:

13 meters

HCF must notify the Commission when licensed operation is restored. HCF must use whatever means are necessary to protect workers and the public from exposure to radio frequency radiation in excess of the Commission's exposure guidelines. *See* 47 CFR § 1.1310.

This authority expires on August 16, 2011.

STA Advisory: Section 309(f) of the Communications Act of 1934, as amended, authorizes the Commission to grant STA in cases of "extraordinary circumstances requiring temporary authorizations in the public interest and when delay in the institution of the temporary operations would seriously prejudice the public interest." However, Section 309(f) is not a means by which a licensee/permittee may circumvent established processing procedures which require the filing of an application, nor is it a means by which a broadcaster may enhance his facility or make operation more convenient for the broadcaster. Stations operating with less than licensed facilities under temporary authorities can be viewed as receiving the benefit of a larger protection area than that in which they are currently providing service.

Accordingly, Special Temporary Authorities by nature are to be temporary and are not intended for extended use. Licensees of stations operating under temporary authorities are reminded that timely restoration of permanent facilities is the responsibility of the licensee and should be undertaken expeditiously. Any request for extension of special temporary authorities carries an increased burden with each subsequent request.

Therefore, requests for extension of STA will be granted only where the licensee can show that one or more of the following criteria have been met:

- Restoration of licensed facilities is complete and testing is underway;
- Substantial progress has been made during the most recent STA period toward restoration of licensed operation; or
- No progress has been made during the most recent STA period for reasons clearly beyond the licensee's control, and the licensee has taken all possible steps to expeditiously resolve the problem.

Sincerely,

Charles N. Miller, Engineer

Audio Division Media Bureau

cc: Horizon Christian Fellowship